

AERA/AERSCO
AERA Technical Services Department
500 Coventry Lane, Suite 180 Crystal Lake IL 60014
Phone 888/324-2372 Fax 888/329-2372

TECHNICAL BULLETIN		Mfg: FORD
	March 2006	Model: TRUCK
	TB 2201R	Liter: 6.0L
		V I N: P
		Year: 02-09

Cylinder Head Installation For
2003-2005 Ford 6.0L Diesel Engines

The AERA Technical Committee offers the following information regarding cylinder head installation for 2003-2005 Ford 6.0L diesel engines. This bulletin is being revised to reflect changes to the head bolt torque sequence originally published. This engine utilizes fifteen bolts to secure each head to the cylinder block, ten M14 and five M8 bolts. Before installing the cylinder heads, it is important to obtain new M14 head bolts; the M8 bolts may be reused if they're undamaged.

NOTE: To prevent engine damage, you must always REPLACE all M14 x 192 cylinder head bolts when installing the cylinder head. Lightly lubricate M14 x 192 bolt threads and mating surfaces of bolt flanges with clean engine oil. Too much oil will cause hydrostatic lock and give incorrect torque reading. Do not lubricate the M8 x 70 bolts.

Do not use anti-seize compounds, grease, or any other lubricant except engine oil. Other lubricants have an adverse effect on torque results. Follow the steps listed below to correctly install this engine's cylinder heads. Refer to Figure 1 below for the proper sequences.

M14 Bolts

1. Torque lubricated bolts in the sequence numbered 1 through 10 to 65 ft/lbs (88Nm).
2. Torque all bolts in sequence numbered 1 through 10 to 85 ft/lbs (116 Nm).
3. Torque all bolts in sequence numbered 1 through 10, clockwise 90°.
4. Torque all bolts in sequence numbered 1 through 10, a second time clockwise 90°.
5. Torque all bolts in sequence numbered 1 through 10, a third time clockwise 90°.

M8 Bolts - DO NOT LUBRICATE M8 BOLTS

This information is provided from the best available sources. However, AERA does not assume responsibility for data accuracy or consequences of its application. Members and others are not authorized to reproduce or distribute this material in any form, or issue it to their branches, divisions, or subsidiaries, etc. at a different location, without written permission.
© Copyright AERA 2006



Reference:	
-------------------	--

TECHNICAL BULLETIN




March 2006
TB 2201R

Mfg: FORD
Model: TRUCK
Liter: 6.0L
VIN: P
Year: 02-09

1. Torque all M8 bolts in the sequence numbered 11 through 15 to 18 ft/lbs (24 Nm).
2. Torque all M8 bolts in the sequence numbered 11 through 15 to 23 ft/lbs (31 Nm).

The AERA Technical Committee

Bulletin Diagram: FIGURE 1. CYLINDER HEAD BOLT TORQUE SEQUENCE - CYLINDER HEAD



This information is provided from the best available sources. However, AERA does not assume responsibility for data accuracy or consequences of its application. Members and others are not authorized to reproduce or distribute this material in any form, or issue it to their branches, divisions, or subsidiaries, etc. at a different location, without written permission.
© Copyright AERA 2006



Reference: